Materials Management Department
Rec'd 24 MAR 3 0 2009
MODE: SS | SH | DC | RO
BUYER:
SECTION CHIEF:

BATANGAS COAL-FIRED THERMAL PP
San Rafael, Calaca, Batangas

PB090815 - Am 6209

PR NO.
TB-BCM08-281
Use this Number in all communication

PURCHASE REQUISITION

Requisitioning Office : BATANGAS COAL FIRED MAINTENANCE
Cost Center Number : 5255013 Local :
GL No. : 101 OE No.:
WO No. : JO No. :

Date : 11/07/08
Date Needed : 02/05/09
Deliver to : NPC-BCFTPP, Calaca, Batangas
Date PR Rcvd. by Proc Office:

ITEM NO.	NSN	COMPLETE DESCRIPTION/SPECIFICATION	QUANTITY	U/M	ESTIMATED COST	ASSIGNED PO/IO NO.
		ELECTROSTATIC PRECIPITATOR SPARE PARTS				
1	N02346524	(ME) SUPPORT INSULATOR	4	PC	1,108,800.00	
2	N02346525	(ME) BUSHING INSULATOR	4	PC	1,307,980.00	
3	N02346526	(ME) SHAFT INSULATOR	4	PC.	1,079,680.00	
4	N02346527	(ME) RAPPER INSULATORS W/BUSHING	4	PC.	1,780,000.00	
5	N02346528	(ME) DE BEARING	84	PC.	4,746,000.00	
6	N02346529	(ME) LINK MECHANISM	7	PC.	478,156.00	
7	N02346530	(ME) DE HAMMER	1	PC.	46,592.00	
8	N02346531	(ME) CE HAMMER	1	PC.	46,592.00	
9	N02346532	(ME) PROTECTION CONDUIT	8	PC.	2,240,000.00	
				PHP	12,833,800.00	

Notes:
1. Included in PPMP 2008;
2. Cost is based from supplier quotation dated February, 2008;
3. Bidders must submit assembly drawing showing above parts;
4. Bidders must submit Authority to Bid from the manufacturer;
5. Manufacturer must be acceptable to NPC;
6. Manufacturer must provide installation assistance;
7. Bidders must conduct Site Inspection and Submit Certificate;
8. Above parts are for Mitsubishi EP :
   SN: B-1937/1938
   SPIN: FG201 ESPO1/02
   YEAR: 1995

Approved for Purchase:

D. S. SEDILLA
VP – Visayas Generation,
BMGPP & BCFTPP

PURPOSE/REMARKS Requisitioned items will replace Unit-2 worn out & corroded EP parts based on actual inspection during 2007 APO.

Attachments :	Requisitioned by :	Approved for Purchase
IR, PPMP	O. Q. QUERUBIN/E.F.TAN Print Name & Position Superintendent A - Mechanical/Maint.Manager Date	[illegible] CALDE Print Name & Position Plant Manager Date